



S21/S31 Software V2.3.1 Release Notes (April 2019)

S21/31 Fixes

- Panner % value was not being displayed correctly.
- Master fader not working correctly if Disable Mute was active.
- Unit labels intermittently not being displayed.
- No response of Aux Send controls when being adjusted in Aux to Fader mode if done very quickly after assignment (the fix is new worksurface code V66).
- Compressor names overlapping title area.
- Crossfade & AMM global scope toggle not working correctly.
- Dynamics mode selector staying open after new session.